

CAR REPORT



VW Polo 2014 Highline 1.2

₹ 425000

Volkswagen Polo HIGHLINE1.2L (P)

₹ 425000



51000



Petrol



Manual



Grey



Pune














[Link to Gallery - https://benimcars.com/buy-car/10/gallery](https://benimcars.com/buy-car/10/gallery)

| | | | |
|---------------------------|-----------|----------------------|-----------|
| Year | 2014 | Register Year | 2014 |
| Manufacture Year | 2014 | RTO | MH46 |
| Insurance Validity | Sept 2024 | Ownership | 1st Owner |
| Fuel Type | Petrol | Color | Grey |
| Transmission | Manual | Seat | 5 Seater |
| Kms Driven | 51000 Kms | Place | Pune |

CAR INSPECTION REPORT

Exterior

| Name | Status |
|--|---|
| No body parts have been repaired |  |
| No corrosion in body panels |  |
| No body parts have been replaced |  |
| No cracks in rims and alloys |  |
| No dents in rims and alloys |  |
| No repair in pillars |  |
| Turn signal lights working fine |  |
| There is dent on Front right door |  |
| There is scratch on Front Bumper, Bonnet, Front right door, Rear right door, Rear left door and Roof |  |
| Rear Bumper have cracks. |  |
| |  |


| | |
|--|--|
| Front Bumper,Right Quarter panel,Rear Bumper,Left Quarter panel,Left running board and Boot/Dicky door are Repainted | |
|--|--|

Interior





| Name | Status |
|--|--------|
| Upholstery is in good condition | ✓ |
| Central locking system is working fine | ✓ |
| Roof lining is in good condition | ✓ |
| Carpet and floor mats are free of cuts and tears | ✓ |
| All functions in cluster panel are working fine | ✓ |
| AC blower operates as designed | ✓ |

Engine


| Name | Status |
|-------------------------------------|--------|
| Engine starting in single crank | ✓ |
| Battery is in good condition | ✓ |
| Car has no white or black smoke | ✓ |
| Engine has no abnormal noise | ✓ |
| Engine has no back compression | ✓ |
| Radiator is in good condition | ✓ |
| Coolant is free of foreign material | ✓ |
| Ignition system is working fine | ✓ |
| Steering system working properly | ✓ |
| Alternator belt is working smoothly | ✓ |
| Wiper working smoothly | ✓ |

| | |
|-----------------------------------|---|
| AC compressor is working smoothly |  |
|-----------------------------------|---|



RoadTest

| Name | Status |
|-----------------------------------|---|
| Steering is perfectly aligned |  |
| Engine exhibits appropriate power |  |
| Engine exhibits appropriate power |  |
| Gear shift is operating smoothly |  |

Underbody


| Name | Status |
|--|---|
| Main oil seal has no sign of oil leaks |  |

Tyres

| Name | Status |
|------------------|---|
| Right Front Tyre |  |
| Left Front Tyre |  |
| Right Back Tyre |  |
| Left Back Tyre |  |
| Spare Tyre |  |

CAR FEATURE REPORT

ENTERTAINMENT_COMMUNICATION

| Name | Status |
|----------------------------------|---|
| Touch Screen Infotainment System |  |

| | |
|--------------------------------------|---|
| Integrated 2DIN Audio | ✓ |
| Bluetooth Compatibility/Connectivity | ✓ |
| Speakers | ✓ |
| AM/FM Radio | ✓ |
| Integrated(in-dash) Music System | ✓ |
| GPS Navigation System | ✓ |
| Heads Up Display(HUD) | ✓ |
| Auto CD Changer | ✓ |
| Audio System Remote Control | ✓ |
| CD Player | ✓ |
| Internal Storage/Hard Drive | ✓ |

EXTERIOR

| Name | Status |
|----------------------------------|--------|
| Rear Wiper | ✓ |
| Rear Defogger | ✓ |
| Headlamps - Projectors | ✓ |
| Outside Rear View Mirrors(ORVMs) | ✓ |
| Rear Power Window | ✓ |
| Body Colored Bumpers | ✓ |
| Turn Indicators on ORVM | ✓ |
| Fog Lamps | ✓ |
| Roof Rails | ✓ |
| Side Stepper | ✓ |

| | |
|---------------------------------|---|
| Rear Spoiler | ✓ |
| Sunroof | ✓ |
| Tinted Glass | ✓ |
| Rain Sensing Wipers | ✓ |
| Roof Carrier | ✓ |
| Xenon Headlamps / HID-headlamps | ✓ |
| Chrome Grille | ✓ |
























SAFETY

| Name | Status |
|-------------------------------|--------|
| Airbags | ✓ |
| Follow Me Home Headlamps | ✓ |
| Child Seat Anchor Points | ✓ |
| Anti-Lock Braking System(ABS) | ✓ |
| Engine Immobilizer | ✓ |
| Anti Theft Alarm | ✓ |
| Front Impact Beams | ✓ |
| Central Locking | ✓ |
| Rear Seat Belts | ✓ |
| Headlight Height Adjuster | ✓ |
| Seat Belt Warning | ✓ |
| Speed Sensing Door Lock | ✓ |
| Child Safety Lock | ✓ |
| Low Fuel level Warning | ✓ |

| | |
|---|---|
| Door Ajar Warning | ✓ |
| Engine Check Warning | ✓ |
| Electronic Stability Program(ESP) | ✓ |
| Knee Airbags | ✓ |
| Brake Assist(BA) | ✓ |
| 360 View Camera | ✓ |
| Blind Spot Monitor | ✓ |
| Automatic Head Lamps | ✓ |
| Tyre Pressure Monitoring System (TPMS) | ✓ |
| Hill Hold Control | ✓ |
| Hill Assist | ✓ |
| Rear Camera | ✓ |
| Hill Descent Control | ✓ |
| Electronic Brake Force Distribution (EBD) | ✓ |
| Middle Rear Three-Point Seatbelt | ✓ |
| Middle Rear Headrest | ✓ |
| Clutch Lock | ✓ |
| Impact Sensing Auto Door Unlock | ✓ |

COMFORT_CONVENIENCE






| Name | Status |
|---------------------------|---------------|
| Cruise Control | ✓ |
| Automatic Climate Control | ✓ |
| Rear AC Vents | ✓ |


| | |
|-----------------------------|---|
| Anti-Glare Mirrors - Manual |  |
| Steering Mounted Controls |  |
| Armrest |  |
| Power Windows |  |
| Air Conditioner |  |
| Power Steering |  |
| 12V Power Outlets |  |
| Vanity Mirror on Sun Visors |  |
| Seat Lumbar Support |  |
| Cup Holders |  |
| Adjustable Headrests |  |
| Lane Change Indicator |  |
| Gear Indicator |  |
| Rear Reading Lamp |  |
| Heater |  |
| Boot Lid Opener |  |
| Remote Fuel Lid Opener |  |
| Clock |  |
| Voice Command/Control |  |
| Electronic |  |
| Ventilated Seats |  |
| Ventilated Seats Rear |  |
| Traction Control |  |


| | |
|----------------------------------|---|
| Steering Wheel Gearshift Paddles | ✓ |
| Keyless Start | ✓ |
| Glove Box Cooling | ✓ |
| Rear Seat Centre Arm Rest | ✓ |
| Keyless Entry | ✓ |
| Trunk Light | ✓ |
| Remote Trunk Opener | ✓ |
| Rear Window Blind | ✓ |
| Luggage Hook and Net | ✓ |
| Battery Saver | ✓ |

INTERIOR

| Name | Status |
|--|--------|
| Tachometer | ✓ |
| Height Adjustable Driver Seat - Manual | ✓ |
| Seat Upholstery | ✓ |
| Folding Rear Seat | ✓ |
| Instrument Cluster | ✓ |
| Seat Adjustment | ✓ |
| Glove Compartment | ✓ |
| Interior Door Handles | ✓ |
| Air Quality Control/filter | ✓ |
| Electrically Adjustable Driver Seat | ✓ |
| Leather Seats | ✓ |

| | |
|--------------------------------|---|
| Leather-Wrapped Steering Wheel |  |
| Folding Table In The Rear |  |
| Dual Tone Dashboard |  |
| Outside Temperature Display |  |
| Cigarette Lighter |  |

 +91 846 881 7758

 contact@benimcars.com

 benimcars.com