





Link to Gallery - https://benimcars.com/buy-car/11/gallery

| Year | 2014 | Register Year | 2014 |
|-----------------------|-----------|---------------|-----------|
| Manufacture Year | 2014 | RTO | MH02 |
| Insurance Validity | Oct 2024 | Ownership | 1st Owner |
| Fuel Type | Petrol | Color | Black |
| Transmission | Automatic | Seat | 5 Seater |
| Kms Driven | 45000 Kms | Place | Pune |
| | | | |

CAR INSPECTION REPORT

Exterior

| Name | Status |
|--|---------|
| No body parts have been repaired | \odot |
| No corrosion in body panels | \odot |
| No body parts have been replaced | \odot |
| No cracks in rims and alloys | \odot |
| No dents in rims and alloys | \odot |
| No repair in pillars | \odot |
| Turn signal lights working fine | \odot |
| There is dent on Front right door | \odot |
| There is scratch on Front Bumper,Bonnet,Front right door,Rear right door,Rear left door and Roof | \odot |
| Rear Bumper have cracks. | \odot |
| | \odot |

Interior

| Name | Status |
|--|---------|
| Upholstery is in good condition | \odot |
| Central locking system is working fine | \odot |
| Roof lining is in good condition | \odot |
| Carpet and floor mats are free of cuts and tears | \odot |
| All functions in cluster panel are working fine | \odot |
| AC blower operates as designed | \odot |

Engine

| Name | Status |
|-------------------------------------|---------|
| Engine starting in single crank | \odot |
| Battery is in good condition | \odot |
| Car has no white or black smoke | \odot |
| Engine has no abnormal noise | \odot |
| Engine has no back compression | \odot |
| Radiator is in good condition | \odot |
| Coolant is free of foreign material | \odot |
| Ignition system is working fine | \odot |
| Steering system working properly | \odot |
| Alternator belt is working smoothly | \odot |
| Wiper working smoothly | \odot |

| AC compressor is working smoothly | \odot |
|-----------------------------------|---------|
|-----------------------------------|---------|

RoadTest

| Name | Status |
|-----------------------------------|---------|
| Steering is perfectly aligned | \odot |
| Engine exhibits appropriate power | \odot |
| Engine exhibits appropriate power | \odot |
| Gear shift is operating smoothly | \odot |

Underbody

| Name | Status |
|--|---------|
| Main oil seal has no sign of oil leaks | \odot |

Tyres

| Name | Status |
|------------------|---------|
| Right Front Tyre | \odot |
| Left Front Tyre | \odot |
| Right Back Tyre | \odot |
| Left Back Tyre | \odot |
| Spare Tyre | \odot |

CAR FEATURE REPORT

ENTERTAINMENT_COMMUNICATION

| Name | Status |
|----------------------------------|------------|
| Touch Screen Infotainment System | \bigcirc |

| Integrated 2DIN Audio | \odot |
|--------------------------------------|---------|
| Bluetooth Compatibility/Connectivity | \odot |
| Speakers | \odot |
| AM/FM Radio | \odot |
| Integrated(in-dash) Music System | \odot |
| GPS Navigation System | \odot |
| Heads Up Display(HUD) | \odot |
| Auto CD Changer | \odot |
| Audio System Remote Control | \odot |
| CD Player | \odot |
| Internal Storage/Hard Drive | \odot |

EXTERIOR

| Name | Status |
|----------------------------------|---------|
| Rear Wiper | \odot |
| Rear Defogger | \odot |
| Headlamps - Projectors | \odot |
| Outside Rear View Mirrors(ORVMs) | \odot |
| Rear Power Window | \odot |
| Body Colored Bumpers | \odot |
| Turn Indicators on ORVM | \odot |
| Fog Lamps | \odot |
| Roof Rails | \odot |
| Side Stepper | \odot |

| Rear Spoiler | \odot |
|---------------------------------|---------|
| Sunroof | \odot |
| Tinted Glass | \odot |
| Rain Sensing Wipers | \odot |
| Roof Carrier | \odot |
| Xenon Headlamps / HID-headlamps | \odot |
| Chrome Grille | \odot |

SAFETY

| Name | Status |
|-------------------------------|---------|
| Airbags | \odot |
| Follow Me Home Headlamps | \odot |
| Child Seat Anchor Points | \odot |
| Anti-Lock Braking System(ABS) | \odot |
| Engine Immobilizer | \odot |
| Anti Theft Alarm | \odot |
| Front Impact Beams | \odot |
| Central Locking | \odot |
| Rear Seat Belts | \odot |
| Headlight Height Adjuster | \odot |
| Seat Belt Warning | \odot |
| Speed Sensing Door Lock | \odot |
| Child Safety Lock | \odot |
| Low Fuel level Warning | \odot |

| Door Ajar Warning | \odot |
|---|---------|
| Engine Check Warning | \odot |
| Electronic Stability Program(ESP) | \odot |
| Knee Airbags | \odot |
| Brake Assist(BA) | \odot |
| 360 View Camera | \odot |
| Blind Spot Monitor | \odot |
| Automatic Head Lamps | \odot |
| Tyre Pressure Monitoring System (TPMS) | \odot |
| Hill Hold Control | \odot |
| Hill Assist | \odot |
| Rear Camera | \odot |
| Hill Descent Control | \odot |
| Electronic Brake Force Distribution (EBD) | \odot |
| Middle Rear Three-Point Seatbelt | \odot |
| Middle Rear Headrest | \odot |
| Clutch Lock | \odot |
| Impact Sensing Auto Door Unlock | \odot |

COMFORT_CONVENIENCE

| Name | Status |
|---------------------------|---------|
| Cruise Control | \odot |
| Automatic Climate Control | \odot |
| Rear AC Vents | \odot |

| Anti-Glare Mirrors - Manual | \bigcirc |
|-----------------------------|------------|
| Steering Mounted Controls | \odot |
| Armrest | \odot |
| Power Windows | \odot |
| Air Conditioner | \odot |
| Power Steering | \bigcirc |
| 12V Power Outlets | \odot |
| Vanity Mirror on Sun Visors | \odot |
| Seat Lumbar Support | \odot |
| Cup Holders | \odot |
| Adjustable Headrests | \odot |
| Lane Change Indicator | \odot |
| Gear Indicator | \bigcirc |
| Rear Reading Lamp | \bigcirc |
| Heater | \bigcirc |
| Boot Lid Opener | \bigcirc |
| Remote Fuel Lid Opener | \bigcirc |
| Clock | \odot |
| Voice Command/Control | \odot |
| Electronic | \odot |
| Ventilated Seats | \odot |
| Ventilated Seats Rear | \odot |
| Traction Control | \odot |

| Steering Wheel Gearshift Paddles | \odot |
|----------------------------------|---------|
| Keyless Start | \odot |
| Glove Box Cooling | \odot |
| Rear Seat Centre Arm Rest | \odot |
| Keyless Entry | \odot |
| Trunk Light | \odot |
| Remote Trunk Opener | \odot |
| Rear Window Blind | \odot |
| Luggage Hook and Net | \odot |
| Battery Saver | \odot |

INTERIOR

| Name | Status |
|--|------------|
| Tachometer | \odot |
| Height Adjustable Driver Seat - Manual | \odot |
| Seat Upholstery | \odot |
| Folding Rear Seat | \odot |
| Instrument Cluster | \bigcirc |
| Seat Adjustment | \bigcirc |
| Glove Compartment | \odot |
| Interior Door Handles | \odot |
| Air Quality Control/filter | \bigcirc |
| Electrically Adjustable Driver Seat | \odot |
| Leather Seats | \odot |

| Leather-Wrapped Steering Wheel | \odot |
|--------------------------------|------------|
| Folding Table In The Rear | \odot |
| Dual Tone Dashboard | \odot |
| Outside Temperature Display | \odot |
| Cigarette Lighter | \bigcirc |