

# CAR REPORT



## VW Polo 1.6 2011

₹ 315000

Volkswagen Polo HIGHLINE 1.6L (P)

₹ 315000



59000



Petrol



Manual



Red



Pune



[Link to Gallery - https://benimcars.com/buy-car/12/gallery](https://benimcars.com/buy-car/12/gallery)

---












<b>Year</b>	2011	<b>Register Year</b>	2012
<b>Manufacture Year</b>	2011	<b>RTO</b>	MH02
<b>Insurance Validity</b>	June 2024	<b>Ownership</b>	1st Owner
<b>Fuel Type</b>	Petrol	<b>Color</b>	Red
<b>Transmission</b>	Manual	<b>Seat</b>	5 Seater
<b>Kms Driven</b>	59000 Kms	<b>Place</b>	Pune

---

## CAR INSPECTION REPORT







---

### Exterior












Name	Status
No body parts have been repaired	
No corrosion in body panels	
No body parts have been replaced	
No cracks in rims and alloys	
No dents in rims and alloys	
No repair in pillars	
Turn signal lights working fine	
There is dent on Front right door	
There is scratch on Front Bumper, Bonnet, Front right door, Rear right door, Rear left door and Roof	
Rear Bumper have cracks.	
	


Front Bumper,Right Quarter panel,Rear Bumper,Left Quarter panel,Left running board and Boot/Dicky door are Repainted	
--	--

## Interior





Name	Status
Upholstery is in good condition	
Central locking system is working fine	
Roof lining is in good condition	
Carpet and floor mats are free of cuts and tears	
All functions in cluster panel are working fine	
AC blower operates as designed	

## Engine


Name	Status
Engine starting in single crank	
Battery is in good condition	
Car has no white or black smoke	
Engine has no abnormal noise	
Engine has no back compression	
Radiator is in good condition	
Coolant is free of foreign material	
Ignition system is working fine	
Steering system working properly	
Alternator belt is working smoothly	
Wiper working smoothly	

AC compressor is working smoothly	
-----------------------------------	---



## RoadTest

Name	Status
Steering is perfectly aligned	
Engine exhibits appropriate power	
Engine exhibits appropriate power	
Gear shift is operating smoothly	

## Underbody

Name	Status
Main oil seal has no sign of oil leaks	


## Tyres

Name	Status
Right Front Tyre	
Left Front Tyre	
Right Back Tyre	
Left Back Tyre	
Spare Tyre	

# CAR FEATURE REPORT

---

## ENTERTAINMENT\_COMMUNICATION

Name	Status
Touch Screen Infotainment System	

Integrated 2DIN Audio	✓
Bluetooth Compatibility/Connectivity	✓
Speakers	✓
AM/FM Radio	✓
Integrated(in-dash) Music System	✓
GPS Navigation System	✓
Heads Up Display(HUD)	✓
Auto CD Changer	✓
Audio System Remote Control	✓
CD Player	✓
Internal Storage/Hard Drive	✓

## EXTERIOR

Name	Status
Rear Wiper	✓
Rear Defogger	✓
Headlamps - Projectors	✓
Outside Rear View Mirrors(ORVMs)	✓
Rear Power Window	✓
Body Colored Bumpers	✓
Turn Indicators on ORVM	✓
Fog Lamps	✓
Roof Rails	✓
Side Stepper	✓

Rear Spoiler	✓
Sunroof	✓
Tinted Glass	✓
Rain Sensing Wipers	✓
Roof Carrier	✓
Xenon Headlamps / HID-headlamps	✓
Chrome Grille	✓

## SAFETY

Name	Status
Airbags	✓
Follow Me Home Headlamps	✓
Child Seat Anchor Points	✓
Anti-Lock Braking System(ABS)	✓
Engine Immobilizer	✓
Anti Theft Alarm	✓
Front Impact Beams	✓
Central Locking	✓
Rear Seat Belts	✓
Headlight Height Adjuster	✓
Seat Belt Warning	✓
Speed Sensing Door Lock	✓
Child Safety Lock	✓
Low Fuel level Warning	✓

Door Ajar Warning	✓
Engine Check Warning	✓
Electronic Stability Program(ESP)	✓
Knee Airbags	✓
Brake Assist(BA)	✓
360 View Camera	✓
Blind Spot Monitor	✓
Automatic Head Lamps	✓
Tyre Pressure Monitoring System (TPMS)	✓
Hill Hold Control	✓
Hill Assist	✓
Rear Camera	✓
Hill Descent Control	✓
Electronic Brake Force Distribution (EBD)	✓
Middle Rear Three-Point Seatbelt	✓
Middle Rear Headrest	✓
Clutch Lock	✓
Impact Sensing Auto Door Unlock	✓

## **COMFORT\_CONVENIENCE**

<b>Name</b>	<b>Status</b>
Cruise Control	✓
Automatic Climate Control	✓
Rear AC Vents	✓






Anti-Glare Mirrors - Manual	✓
Steering Mounted Controls	✓
Armrest	✓
Power Windows	✓
Air Conditioner	✓
Power Steering	✓
12V Power Outlets	✓
Vanity Mirror on Sun Visors	✓
Seat Lumbar Support	✓
Cup Holders	✓
Adjustable Headrests	✓
Lane Change Indicator	✓
Gear Indicator	✓
Rear Reading Lamp	✓
Heater	✓
Boot Lid Opener	✓
Remote Fuel Lid Opener	✓
Clock	✓
Voice Command/Control	✓
Electronic	✓
Ventilated Seats	✓
Ventilated Seats Rear	✓
Traction Control	✓




Steering Wheel Gearshift Paddles	✓
Keyless Start	✓
Glove Box Cooling	✓
Rear Seat Centre Arm Rest	✓
Keyless Entry	✓
Trunk Light	✓
Remote Trunk Opener	✓
Rear Window Blind	✓
Luggage Hook and Net	✓
Battery Saver	✓


## INTERIOR

Name	Status
Tachometer	✓
Height Adjustable Driver Seat - Manual	✓
Seat Upholstery	✓
Folding Rear Seat	✓
Instrument Cluster	✓
Seat Adjustment	✓
Glove Compartment	✓
Interior Door Handles	✓
Air Quality Control/filter	✓
Electrically Adjustable Driver Seat	✓
Leather Seats	✓

Leather-Wrapped Steering Wheel	
Folding Table In The Rear	
Dual Tone Dashboard	
Outside Temperature Display	
Cigarette Lighter	

---

 +91 846 881 7758

 [contact@benimcars.com](mailto:contact@benimcars.com)

 [benimcars.com](http://benimcars.com)