

CAR REPORT



Hyundai Verna 1.6 SX (O) AT Petrol ₹ 920000

Hyundai Verna 1.6 VTVT SX (O) AT

₹ 919999



22500



Petrol



Automatic



Red



Pune














[Link to Gallery - https://benimcars.com/buy-car/17/gallery](https://benimcars.com/buy-car/17/gallery)

Year	2018	Register Year	2018
Manufacture Year	2018	RTO	MH 02
Insurance Validity	Comprehensive insurance April 2025	Ownership	1st Owner



Fuel Type	Petrol	Color	Red
Transmission	Automatic	Seat	5 Seater
Kms Driven	22500 Kms	Place	Pune

CAR INSPECTION REPORT

Exterior

Name	Status
No body parts have been repaired	
No corrosion in body panels	
No body parts have been replaced	
No cracks in rims and alloys	
No dents in rims and alloys	
No repair in pillars	
Turn signal lights working fine	
There is dent on Front right door	
There is scratch on Front Bumper, Bonnet, Front right door, Rear right door, Rear left door and Roof	
Rear Bumper have cracks.	
Front Bumper, Right Quarter panel, Rear Bumper, Left Quarter panel, Left running board and Boot/Dicky door are Repainted	

Interior

Name	Status
Upholstery is in good condition	
Central locking system is working fine	


Roof lining is in good condition	✓
Carpet and floor mats are free of cuts and tears	✓
All functions in cluster panel are working fine	✓
AC blower operates as designed	✓

Engine


Name	Status
Engine starting in single crank	✓
Battery is in good condition	✓
Car has no white or black smoke	✓
Engine has no abnormal noise	✓
Engine has no back compression	✓
Radiator is in good condition	✓
Coolant is free of foreign material	✓
Ignition system is working fine	✓
Steering system working properly	✓
Alternator belt is working smoothly	✓
Wiper working smoothly	✓
AC compressor is working smoothly	✓

RoadTest



Name	Status
Steering is perfectly aligned	✓
Engine exhibits appropriate power	✓
Engine exhibits appropriate power	✓

Gear shift is operating smoothly	
----------------------------------	---

Underbody








Name	Status
Main oil seal has no sign of oil leaks	

Tyres

Name	Status
Right Front Tyre	
Left Front Tyre	
Right Back Tyre	
Left Back Tyre	
Spare Tyre	

CAR FEATURE REPORT


ENTERTAINMENT_COMMUNICATION

Name	Status
Touch Screen Infotainment System	
Integrated 2DIN Audio	
Bluetooth Compatibility/Connectivity	
Speakers	
AM/FM Radio	
Integrated(in-dash) Music System	
GPS Navigation System	





















Heads Up Display(HUD)	✓
Auto CD Changer	✓
Audio System Remote Control	✓
CD Player	✓
Internal Storage/Hard Drive	✓

EXTERIOR

Name	Status
Rear Wiper	✓
Rear Defogger	✓
Headlamps - Projectors	✓
Outside Rear View Mirrors(ORVMs)	✓
Rear Power Window	✓
Body Colored Bumpers	✓
Turn Indicators on ORVM	✓
Fog Lamps	✓
Roof Rails	✓
Side Stepper	✓
Rear Spoiler	✓
Sunroof	✓
Tinted Glass	✓
Rain Sensing Wipers	✓
Roof Carrier	✓
Xenon Headlamps / HID-headlamps	✓

Chrome Grille	
---------------	---























SAFETY

Name	Status
Airbags	
Follow Me Home Headlamps	
Child Seat Anchor Points	
Anti-Lock Braking System(ABS)	
Engine Immobilizer	
Anti Theft Alarm	
Front Impact Beams	
Central Locking	
Rear Seat Belts	
Headlight Height Adjuster	
Seat Belt Warning	
Speed Sensing Door Lock	
Child Safety Lock	
Low Fuel level Warning	
Door Ajar Warning	
Engine Check Warning	
Electronic Stability Program(ESP)	
Knee Airbags	
Brake Assist(BA)	
360 View Camera	

Blind Spot Monitor	✓
Automatic Head Lamps	✓
Tyre Pressure Monitoring System (TPMS)	✓
Hill Hold Control	✓
Hill Assist	✓
Rear Camera	✓
Hill Descent Control	✓
Electronic Brake Force Distribution (EBD)	✓
Middle Rear Three-Point Seatbelt	✓
Middle Rear Headrest	✓
Clutch Lock	✓
Impact Sensing Auto Door Unlock	✓

COMFORT_CONVENIENCE

Name	Status
Cruise Control	✓
Automatic Climate Control	✓
Rear AC Vents	✓
Anti-Glare Mirrors - Manual	✓
Steering Mounted Controls	✓
Armrest	✓
Power Windows	✓
Air Conditioner	✓
Power Steering	✓

12V Power Outlets	
Vanity Mirror on Sun Visors	
Seat Lumbar Support	
Cup Holders	
Adjustable Headrests	
Lane Change Indicator	
Gear Indicator	
Rear Reading Lamp	
Heater	
Boot Lid Opener	
Remote Fuel Lid Opener	
Clock	
Voice Command/Control	
Electronic	
Ventilated Seats	
Ventilated Seats Rear	
Traction Control	
Steering Wheel Gearshift Paddles	
Keyless Start	
Glove Box Cooling	
Rear Seat Centre Arm Rest	
Keyless Entry	
Trunk Light	

Remote Trunk Opener	✓
Rear Window Blind	✓
Luggage Hook and Net	✓
Battery Saver	✓

INTERIOR

Name	Status
Tachometer	✓
Height Adjustable Driver Seat - Manual	✓
Seat Upholstery	✓
Folding Rear Seat	✓
Instrument Cluster	✓
Seat Adjustment	✓
Glove Compartment	✓
Interior Door Handles	✓
Air Quality Control/filter	✓
Electrically Adjustable Driver Seat	✓
Leather Seats	✓
Leather-Wrapped Steering Wheel	✓
Folding Table In The Rear	✓
Dual Tone Dashboard	✓
Outside Temperature Display	✓
Cigarette Lighter	✓