# **CAR REPORT**



## Tata Safari XZA Plus

₹ 2195000

Tata Safari XZA PLUS 6S

₹ 2195000












31000

Diesel

Automatic

White

Pune



Link to Gallery - https://benimcars.com/buy-car/19/gallery

Year	2022	Register Year	2022
Manufacture Year	2022	RTO	MH 12
Insurance Validity	Jan 2025	Ownership	1st Owner
Fuel Type	Diesel	Color	White

**Kms Driven** 31000 Kms **Place** Pune

## **CAR INSPECTION REPORT**

#### **Exterior**

Name	Status
No body parts have been repaired	<b>②</b>
No corrosion in body panels	<b>②</b>
No body parts have been replaced	<b>②</b>
No cracks in rims and alloys	<b>②</b>
No dents in rims and alloys	<b>②</b>
No repair in pillars	<b>②</b>
Turn signal lights working fine	<b>②</b>
Minor Scratches	<b>②</b>
Left Rear Door is Repainted	<b>②</b>

### Interior

Name	Status
Upholstery is in good condition	<b>②</b>
Central locking system is working fine	<b>②</b>
Roof lining is in good condition	<b>②</b>
Carpet and floor mats are free of cuts and tears	<b>②</b>
All functions in cluster panel are working fine	<b>②</b>
AC blower operates as designed	<b>②</b>

# **Engine**

Name	Status
Engine starting in single crank	<b>②</b>
Battery is in good condition	<b>②</b>
Car has no white or black smoke	<b>⊘</b>
Engine has no abnormal noise	<b>②</b>
Engine has no back compression	<b>②</b>
Radiator is in good condition	<b>②</b>
Coolant is free of foreign material	<b>②</b>
Ignition system is working fine	<b>②</b>
Steering system working properly	<b>②</b>
Alternator belt is working smoothly	<b>②</b>
Wiper working smoothly	<b>②</b>
AC compressor is working smoothly	<b>②</b>

## RoadTest

Name	Status
Steering is perfectly aligned	<b>②</b>
Engine exhibits appropriate power	<b>②</b>
Engine exhibits appropriate power	<b>②</b>
Gear shift is operating smoothly	<b>②</b>

# **Underbody**

Name	Status
Main oil seal has no sign of oil leaks	<b>⊘</b>

### **Tyres**

Name	Status
Right Front Tyre	<b>②</b>
Left Front Tyre	<b>②</b>
Right Back Tyre	<b>⊘</b>
Left Back Tyre	<b>②</b>
Spare Tyre	<b>②</b>

# **CAR FEATURE REPORT**

## **ENTERTAINMENT\_COMMUNICATION**

Name	Status
Touch Screen Infotainment System	<b>⊘</b>
Integrated 2DIN Audio	<b>②</b>
Bluetooth Compatibility/Connectivity	<b>②</b>
Speakers	<b>②</b>
AM/FM Radio	<b>②</b>
Integrated(in-dash) Music System	<b>②</b>
GPS Navigation System	<b>②</b>
Heads Up Display(HUD)	<b>②</b>
Auto CD Changer	<b>②</b>
Audio System Remote Control	<b>②</b>
CD Player	<b>②</b>
Internal Storage/Hard Drive	<b>⊘</b>

### **EXTERIOR**

Name	Status
Rear Wiper	<b>②</b>
Rear Defogger	<b>②</b>
Headlamps - Projectors	<b>(</b>
Outside Rear View Mirrors(ORVMs)	<b>(</b>
Rear Power Window	<b>⊘</b>
Body Colored Bumpers	<b>⊘</b>
Turn Indicators on ORVM	<b>②</b>
Fog Lamps	<b>⊘</b>
Roof Rails	<b>(</b>
Side Stepper	<b>(</b>
Rear Spoiler	<b>②</b>
Sunroof	<b>(</b>
Tinted Glass	<b>(</b>
Rain Sensing Wipers	<b>(</b>
Roof Carrier	<b>②</b>
Xenon Headlamps / HID-headlamps	<b>②</b>
Chrome Grille	<b>⊘</b>

### **SAFETY**

Name	Status
Airbags	<b>②</b>
Follow Me Home Headlamps	<b>②</b>

Child Seat Anchor Points	<b>②</b>
Anti-Lock Braking System(ABS)	<b>②</b>
Engine Immobilizer	<b>②</b>
Anti Theft Alarm	<b>(</b>
Front Impact Beams	$\odot$
Central Locking	<b>(</b>
Rear Seat Belts	<b>(</b> )
Headlight Height Adjuster	$\odot$
Seat Belt Warning	<b>(</b>
Speed Sensing Door Lock	<b>②</b>
Child Safety Lock	<b>(</b>
Low Fuel level Warning	$\odot$
Door Ajar Warning	<b>(</b> )
Engine Check Warning	<b>(</b>
Electronic Stability Program(ESP)	<b>②</b>
Knee Airbags	<b>(</b>
Brake Assist(BA)	<b>②</b>
360 View Camera	<b>②</b>
Blind Spot Monitor	<b>②</b>
Automatic Head Lamps	<b>②</b>
Tyre Pressure Monitoring System (TPMS)	<b>②</b>
Hill Hold Control	<b>②</b>
Hill Assist	<b>②</b>

Rear Camera	<b>②</b>
Hill Descent Control	<b>⊘</b>
Electronic Brake Force Distribution (EBD)	<b>②</b>
Middle Rear Three-Point Seatbelt	<b>②</b>
Middle Rear Headrest	<b>②</b>
Clutch Lock	<b>②</b>
Impact Sensing Auto Door Unlock	<b>⊘</b>

# COMFORT\_CONVENIENCE

Name	Status
Cruise Control	<b>(</b>
Automatic Climate Control	<b>②</b>
Rear AC Vents	<b>②</b>
Anti-Glare Mirrors - Manual	<b>②</b>
Steering Mounted Controls	<b>②</b>
Armrest	<b>②</b>
Power Windows	<b>②</b>
Air Conditioner	<b>②</b>
Power Steering	<b>②</b>
12V Power Outlets	<b>②</b>
Vanity Mirror on Sun Visors	<b>②</b>
Seat Lumbar Support	<b>②</b>
Cup Holders	<b>②</b>
Adjustable Headrests	<b>②</b>

Lane Change Indicator	<b>②</b>
Gear Indicator	<b>②</b>
Rear Reading Lamp	<b>(</b>
Heater	<b>(</b>
Boot Lid Opener	<b>(</b> )
Remote Fuel Lid Opener	<b>(</b>
Clock	<b>②</b>
Voice Command/Control	$\odot$
Electronic	<b>②</b>
Ventilated Seats	<b>②</b>
Ventilated Seats Rear	<b>②</b>
Traction Control	<b>②</b>
Steering Wheel Gearshift Paddles	<b>②</b>
Keyless Start	<b>②</b>
Glove Box Cooling	<b>②</b>
Rear Seat Centre Arm Rest	<b>②</b>
Keyless Entry	<b>②</b>
Trunk Light	$\odot$
Remote Trunk Opener	<b>②</b>
Rear Window Blind	<b>②</b>
Luggage Hook and Net	<b>②</b>
Battery Saver	<b>②</b>

## **INTERIOR**

Name	Status
Tachometer	<b>②</b>
Height Adjustable Driver Seat - Manual	<b>②</b>
Seat Upholstery	<b>②</b>
Folding Rear Seat	<b>Ø</b>
Instrument Cluster	<b>Ø</b>
Seat Adjustment	<b>⊘</b>
Glove Compartment	<b>Ø</b>
Interior Door Handles	<b>⊘</b>
Air Quality Control/filter	<b>⊘</b>
Electrically Adjustable Driver Seat	<b>Ø</b>
Leather Seats	<b>⊘</b>
Leather-Wrapped Steering Wheel	<b>Ø</b>
Folding Table In The Rear	<b>⊘</b>
Dual Tone Dashboard	<b>⊘</b>
Outside Temperature Display	<b>②</b>
Cigarette Lighter	<b>②</b>

← +91 846 881 7758 

☐ contact@benimcars.com 

⊕ benimcars.com