

CAR REPORT



Hyundai Creta SX(O) AT Diesel 2020

₹
1710000

Hyundai Creta SX (O) DIESEL

₹ 1710000



24500



Diesel



Automatic



Black



Pune



[Link to Gallery - https://benimcars.com/buy-car/2/gallery](https://benimcars.com/buy-car/2/gallery)

Year	2020	Register Year	2020
Manufacture Year	2020	RTO	MH12
Insurance Validity	July 2024	Ownership	1st Owner
Fuel Type	Diesel	Color	Black
Transmission	Automatic	Seat	5 Seater
Kms Driven	24500 Kms	Place	Pune


CAR INSPECTION REPORT

Exterior













Name	Status
No body parts have been repaired	✓
No corrosion in body panels	✓
No body parts have been replaced	✓
No cracks in rims and alloys	✓
No dents in rims and alloys	✓
No repair in pillars	✓
Turn signal lights working fine	✓
There is dent on Front right door	✓
There is scratch on Front Bumper, Bonnet, Front right door, Rear right door, Rear left door and Roof	✓
Rear Bumper have cracks.	✓
Front Bumper, Right Quarter panel, Rear Bumper, Left Quarter panel, Left running board and Boot/Dicky door are Repainted	✓

Interior





Name	Status
Upholstery is in good condition	✓
Central locking system is working fine	✓
Roof lining is in good condition	✓
Carpet and floor mats are free of cuts and tears	✓
All functions in cluster panel are working fine	✓
AC blower operates as designed	

	
--	---

Engine

Name	Status
Engine starting in single crank	
Battery is in good condition	
Car has no white or black smoke	
Engine has no abnormal noise	
Engine has no back compression	
Radiator is in good condition	
Coolant is free of foreign material	
Ignition system is working fine	
Steering system working properly	
Alternator belt is working smoothly	
Wiper working smoothly	
AC compressor is working smoothly	

RoadTest



Name	Status
Steering is perfectly aligned	
Engine exhibits appropriate power	
Engine exhibits appropriate power	
Gear shift is operating smoothly	

Underbody

Name	Status
------	--------












Main oil seal has no sign of oil leaks	
--	---


Tyres

Name	Status
Right Front Tyre	
Left Front Tyre	
Right Back Tyre	
Left Back Tyre	
Spare Tyre	

CAR FEATURE REPORT

ENTERTAINMENT_COMMUNICATION


Name	Status
Touch Screen Infotainment System	
Integrated 2DIN Audio	
Bluetooth Compatibility/Connectivity	
Speakers	
AM/FM Radio	
Integrated(in-dash) Music System	
GPS Navigation System	
Heads Up Display(HUD)	
Auto CD Changer	
Audio System Remote Control	
CD Player	

Internal Storage/Hard Drive	
-----------------------------	---

EXTERIOR

Name	Status
Rear Wiper	
Rear Defogger	
Headlamps - Projectors	
Outside Rear View Mirrors(ORVMs)	
Rear Power Window	
Body Colored Bumpers	
Turn Indicators on ORVM	
Fog Lamps	
Roof Rails	
Side Stepper	
Rear Spoiler	
Sunroof	
Tinted Glass	
Rain Sensing Wipers	
Roof Carrier	
Xenon Headlamps / HID-headlamps	
Chrome Grille	

SAFETY

Name	Status
Airbags	

Follow Me Home Headlamps	✓
Child Seat Anchor Points	✓
Anti-Lock Braking System(ABS)	✓
Engine Immobilizer	✓
Anti Theft Alarm	✓
Front Impact Beams	✓
Central Locking	✓
Rear Seat Belts	✓
Headlight Height Adjuster	✓
Seat Belt Warning	✓
Speed Sensing Door Lock	✓
Child Safety Lock	✓
Low Fuel level Warning	✓
Door Ajar Warning	✓
Engine Check Warning	✓
Electronic Stability Program(ESP)	✓
Knee Airbags	✓
Brake Assist(BA)	✓
360 View Camera	✓
Blind Spot Monitor	✓
Automatic Head Lamps	✓
Tyre Pressure Monitoring System (TPMS)	✓
Hill Hold Control	✓

Hill Assist	✓
Rear Camera	✓
Hill Descent Control	✓
Electronic Brake Force Distribution (EBD)	✓
Middle Rear Three-Point Seatbelt	✓
Middle Rear Headrest	✓
Clutch Lock	✓
Impact Sensing Auto Door Unlock	✓


COMFORT_CONVENIENCE

Name	Status
Cruise Control	✓
Automatic Climate Control	✓
Rear AC Vents	✓
Anti-Glare Mirrors - Manual	✓
Steering Mounted Controls	✓
Armrest	✓
Power Windows	✓
Air Conditioner	✓
Power Steering	✓
12V Power Outlets	✓
Vanity Mirror on Sun Visors	✓
Seat Lumbar Support	✓
Cup Holders	✓

Adjustable Headrests	✔
Lane Change Indicator	✔
Gear Indicator	✔
Rear Reading Lamp	✔
Heater	✔
Boot Lid Opener	✔
Remote Fuel Lid Opener	✔
Clock	✔
Voice Command/Control	✔
Electronic	✔
Ventilated Seats	✔
Ventilated Seats Rear	✔
Traction Control	✔
Steering Wheel Gearshift Paddles	✔
Keyless Start	✔
Glove Box Cooling	✔
Rear Seat Centre Arm Rest	✔
Keyless Entry	✔
Trunk Light	✔
Remote Trunk Opener	✔
Rear Window Blind	✔
Luggage Hook and Net	✔
Battery Saver	✔

INTERIOR

Name	Status
Tachometer	
Height Adjustable Driver Seat - Manual	
Seat Upholstery	
Folding Rear Seat	
Instrument Cluster	
Seat Adjustment	
Glove Compartment	
Interior Door Handles	
Air Quality Control/filter	
Electrically Adjustable Driver Seat	
Leather Seats	
Leather-Wrapped Steering Wheel	
Folding Table In The Rear	
Dual Tone Dashboard	
Outside Temperature Display	
Cigarette Lighter	

 +91 846 881 7758

 contact@benimcars.com

 benimcars.com