

# CAR REPORT



**Maruti Suzuki Swift VXI AMT 2018**

**₹ 590000**

Maruti Suzuki Swift VXI AMT

₹ 590000



45900



Petrol



Automatic



Red



Pune



[Link to Gallery - https://benimcars.com/buy-car/25/gallery](https://benimcars.com/buy-car/25/gallery)

<b>Year</b>	2018	<b>Register Year</b>	2018
<b>Manufacture Year</b>	2018	<b>RTO</b>	MH 47
<b>Insurance Validity</b>	Zero Dep till April 2025	<b>Ownership</b>	1st Owner
<b>Fuel Type</b>	Petrol	<b>Color</b>	Red

**Transmission**

Automatic **Seat**

5 Seater

**Kms Driven**

45900 Kms **Place**

Pune

---

## CAR INSPECTION REPORT

---

### Exterior

Name	Status
No body parts have been repaired	✓
No corrosion in body panels	✓
No body parts have been replaced	✓
No cracks in rims and alloys	✓
No dents in rims and alloys	✓
No repair in pillars	✓
Turn signal lights working fine	✓
There is dent on Front and rear left door, right fender	✓
Front Bumper, Right Door Rear, Right Door front, Left Fender and Right Quarter Panel are Repainted	✓

### Interior

Name	Status
Upholstery is in good condition	✓
Central locking system is working fine	✓
Roof lining is in good condition	✓
Carpet and floor mats are free of cuts and tears	✓
All functions in cluster panel are working fine	✓
AC blower operates as designed	✓

## Engine

Name	Status
Engine starting in single crank	✓
Battery is in good condition	✓
Car has no white or black smoke	✓
Engine has no abnormal noise	✓
Engine has no back compression	✓
Radiator is in good condition	✓
Coolant is free of foreign material	✓
Ignition system is working fine	✓
Steering system working properly	✓
Alternator belt is working smoothly	✓
Wiper working smoothly	✓
AC compressor is working smoothly	✓

## RoadTest

Name	Status
Steering is perfectly aligned	✓
Engine exhibits appropriate power	✓
Engine exhibits appropriate power	✓
Gear shift is operating smoothly	✓

## Underbody

Name	Status
Main oil seal has no sign of oil leaks	✓

## Tyres

Name	Status
Right Front Tyre	✓
Left Front Tyre	✓
Right Back Tyre	✓
Left Back Tyre	✓
Spare Tyre	✓

## CAR FEATURE REPORT

---


### ENTERTAINMENT\_COMMUNICATION

Name	Status
Touch Screen Infotainment System	✗
Integrated 2DIN Audio	✓
Bluetooth Compatibility/Connectivity	✓
Speakers	✓
AM/FM Radio	✓
Integrated(in-dash) Music System	✓
GPS Navigation System	✗
Heads Up Display(HUD)	✓
Auto CD Changer	✓
Audio System Remote Control	✓
CD Player	✓
Internal Storage/Hard Drive	✓








## EXTERIOR

Name	Status
Rear Wiper	
Rear Defogger	
Headlamps - Projectors	
Outside Rear View Mirrors(ORVMs)	
Rear Power Window	
Body Colored Bumpers	
Turn Indicators on ORVM	
Fog Lamps	
Roof Rails	
Side Stepper	
Rear Spoiler	
Sunroof	
Tinted Glass	
Rain Sensing Wipers	
Roof Carrier	
Xenon Headlamps / HID-headlamps	
Chrome Grille	















## SAFETY























Name	Status
Airbags	
Follow Me Home Headlamps	

Child Seat Anchor Points	
Anti-Lock Braking System(ABS)	
Engine Immobilizer	
Anti Theft Alarm	
Front Impact Beams	
Central Locking	
Rear Seat Belts	
Headlight Height Adjuster	
Seat Belt Warning	
Speed Sensing Door Lock	
Child Safety Lock	
Low Fuel level Warning	
Door Ajar Warning	
Engine Check Warning	
Electronic Stability Program(ESP)	
Knee Airbags	
Brake Assist(BA)	
360 View Camera	
Blind Spot Monitor	
Automatic Head Lamps	
Tyre Pressure Monitoring System (TPMS)	
Hill Hold Control	
Hill Assist	

Rear Camera	
Hill Descent Control	
Electronic Brake Force Distribution (EBD)	
Middle Rear Three-Point Seatbelt	
Middle Rear Headrest	
Clutch Lock	
Impact Sensing Auto Door Unlock	

## COMFORT\_CONVENIENCE


Name	Status
Cruise Control	
Automatic Climate Control	
Rear AC Vents	
Anti-Glare Mirrors - Manual	
Steering Mounted Controls	
Armrest	
Power Windows	
Air Conditioner	
Power Steering	
12V Power Outlets	
Vanity Mirror on Sun Visors	
Seat Lumbar Support	
Cup Holders	
Adjustable Headrests	

Lane Change Indicator	
Gear Indicator	
Rear Reading Lamp	
Heater	
Boot Lid Opener	
Remote Fuel Lid Opener	
Clock	
Voice Command/Control	
Electronic	
Ventilated Seats	
Ventilated Seats Rear	
Traction Control	
Steering Wheel Gearshift Paddles	
Keyless Start	
Glove Box Cooling	
Rear Seat Centre Arm Rest	
Keyless Entry	
Trunk Light	
Remote Trunk Opener	
Rear Window Blind	
Luggage Hook and Net	
Battery Saver	



## INTERIOR

Name	Status
Tachometer	
Height Adjustable Driver Seat - Manual	
Seat Upholstery	
Folding Rear Seat	
Instrument Cluster	
Seat Adjustment	
Glove Compartment	
Interior Door Handles	
Air Quality Control/filter	
Electrically Adjustable Driver Seat	
Leather Seats	
Leather-Wrapped Steering Wheel	
Folding Table In The Rear	
Dual Tone Dashboard	
Outside Temperature Display	
Cigarette Lighter	

 +91 846 881 7758

 [contact@benimcars.com](mailto:contact@benimcars.com)

 [benimcars.com](http://benimcars.com)