

# CAR REPORT



## Honda Brio 2012 S MT

₹ 250000

Honda Brio S MT

₹ 250000



55000



Petrol



Manual



Blue



Pune



[Link to Gallery - https://benimcars.com/buy-car/8/gallery](https://benimcars.com/buy-car/8/gallery)

---

<b>Year</b>	2012	<b>Register Year</b>	2012
<b>Manufacture Year</b>	2012	<b>RTO</b>	MH14
<b>Insurance Validity</b>	Oct 2024	<b>Ownership</b>	1st Owner
<b>Fuel Type</b>	Petrol	<b>Color</b>	Blue
<b>Transmission</b>	Manual	<b>Seat</b>	5 Seater
<b>Kms Driven</b>	55000 Kms	<b>Place</b>	Pune

---

## CAR INSPECTION REPORT

---

### Exterior

Name	Status
No body parts have been repaired	✓
No corrosion in body panels	✓
No body parts have been replaced	✓
No cracks in rims and alloys	✓
No dents in rims and alloys	✓
No repair in pillars	✓
Turn signal lights working fine	✓
There is dent on Front right door	✓
There is scratch on Front Bumper, Bonnet, Front right door, Rear right door, Rear left door and Roof	✓
Rear Bumper have cracks.	✓
	✓


Front Bumper,Right Quarter panel,Rear Bumper,Left Quarter panel,Left running board and Boot/Dicky door are Repainted	
--	--

## Interior





Name	Status
Upholstery is in good condition	✓
Central locking system is working fine	✓
Roof lining is in good condition	✓
Carpet and floor mats are free of cuts and tears	✓
All functions in cluster panel are working fine	✓
AC blower operates as designed	✓

## Engine


Name	Status
Engine starting in single crank	✓
Battery is in good condition	✓
Car has no white or black smoke	✓
Engine has no abnormal noise	✓
Engine has no back compression	✓
Radiator is in good condition	✓
Coolant is free of foreign material	✓
Ignition system is working fine	✓
Steering system working properly	✓
Alternator belt is working smoothly	✓
Wiper working smoothly	✓

AC compressor is working smoothly	
-----------------------------------	---




## RoadTest

Name	Status
Steering is perfectly aligned	
Engine exhibits appropriate power	
Engine exhibits appropriate power	
Gear shift is operating smoothly	

## Underbody

Name	Status
Main oil seal has no sign of oil leaks	


## Tyres

Name	Status
Right Front Tyre	
Left Front Tyre	
Right Back Tyre	
Left Back Tyre	
Spare Tyre	

# CAR FEATURE REPORT

---

## ENTERTAINMENT\_COMMUNICATION

Name	Status
Touch Screen Infotainment System	

Integrated 2DIN Audio	✓
Bluetooth Compatibility/Connectivity	✓
Speakers	✓
AM/FM Radio	✓
Integrated(in-dash) Music System	✓
GPS Navigation System	✓
Heads Up Display(HUD)	✓
Auto CD Changer	✓
Audio System Remote Control	✓
CD Player	✓
Internal Storage/Hard Drive	✓

## EXTERIOR

Name	Status
Rear Wiper	✓
Rear Defogger	✓
Headlamps - Projectors	✓
Outside Rear View Mirrors(ORVMs)	✓
Rear Power Window	✓
Body Colored Bumpers	✓
Turn Indicators on ORVM	✓
Fog Lamps	✓
Roof Rails	✓
Side Stepper	✓

Rear Spoiler	✓
Sunroof	✓
Tinted Glass	✓
Rain Sensing Wipers	✓
Roof Carrier	✓
Xenon Headlamps / HID-headlamps	✓
Chrome Grille	✓
























## SAFETY

Name	Status
Airbags	✓
Follow Me Home Headlamps	✓
Child Seat Anchor Points	✓
Anti-Lock Braking System(ABS)	✓
Engine Immobilizer	✓
Anti Theft Alarm	✓
Front Impact Beams	✓
Central Locking	✓
Rear Seat Belts	✓
Headlight Height Adjuster	✓
Seat Belt Warning	✓
Speed Sensing Door Lock	✓
Child Safety Lock	✓
Low Fuel level Warning	✓

Door Ajar Warning	✓
Engine Check Warning	✓
Electronic Stability Program(ESP)	✓
Knee Airbags	✓
Brake Assist(BA)	✓
360 View Camera	✓
Blind Spot Monitor	✓
Automatic Head Lamps	✓
Tyre Pressure Monitoring System (TPMS)	✓
Hill Hold Control	✓
Hill Assist	✓
Rear Camera	✓
Hill Descent Control	✓
Electronic Brake Force Distribution (EBD)	✓
Middle Rear Three-Point Seatbelt	✓
Middle Rear Headrest	✓
Clutch Lock	✓
Impact Sensing Auto Door Unlock	✓

## **COMFORT\_CONVENIENCE**

<b>Name</b>	<b>Status</b>
Cruise Control	✓
Automatic Climate Control	✓
Rear AC Vents	✓






Anti-Glare Mirrors - Manual	
Steering Mounted Controls	
Armrest	
Power Windows	
Air Conditioner	
Power Steering	
12V Power Outlets	
Vanity Mirror on Sun Visors	
Seat Lumbar Support	
Cup Holders	
Adjustable Headrests	
Lane Change Indicator	
Gear Indicator	
Rear Reading Lamp	
Heater	
Boot Lid Opener	
Remote Fuel Lid Opener	
Clock	
Voice Command/Control	
Electronic	
Ventilated Seats	
Ventilated Seats Rear	
Traction Control	




Steering Wheel Gearshift Paddles	✓
Keyless Start	✓
Glove Box Cooling	✓
Rear Seat Centre Arm Rest	✓
Keyless Entry	✓
Trunk Light	✓
Remote Trunk Opener	✓
Rear Window Blind	✓
Luggage Hook and Net	✓
Battery Saver	✓


## INTERIOR

Name	Status
Tachometer	✓
Height Adjustable Driver Seat - Manual	✓
Seat Upholstery	✓
Folding Rear Seat	✓
Instrument Cluster	✓
Seat Adjustment	✓
Glove Compartment	✓
Interior Door Handles	✓
Air Quality Control/filter	✓
Electrically Adjustable Driver Seat	✓
Leather Seats	✓

Leather-Wrapped Steering Wheel	
Folding Table In The Rear	
Dual Tone Dashboard	
Outside Temperature Display	
Cigarette Lighter	

---

 +91 846 881 7758

 [contact@benimcars.com](mailto:contact@benimcars.com)

 [benimcars.com](http://benimcars.com)